

Not for use without coolant-fluid!

 $Speed\ max.\ (n1/n2) = 6000\ /\ 6000\ [1/min]$

Gear ratio (i)=n1:n2 = 1:1 Pressure (pmax) = 70 [bar] Radial drilling and milling head



60.40VX4SQT15RIK

161064