



### Quick-change angle adapters "Quick"

- Quick and comfortable fixing of angle adapter without tools
- Quick spindle for fixing the quick change angle adapter 627240000 and bit holder 627241000
- Magnetic bit holder with 1/4" (6.35 mm) hexagonal shank
- Suitable for forward and reverse rotation
- Suitable for cordless tools up to a maximum of 100 Nm
- Suitable for all Metabo LT "Quick" machines

Order no.  
EAN code

627077000  
4007430232137