AXA[°]

Quick-change lathe tool post, Type: C



Order data

Order number	318000 C
GTIN	4045197315717
Item class	36A

Description

Application:

Place the lathe tool post with its surface-ground face on to the cross slide in a horizontal position and clamp it. To do this, the bore of the centring plate must have been turned beforehand. Alignment is performed with the boring bar and boring bar holder clamped in position, aligned at right angles to the face plate. Then adjust the pointer to the zero mark of the cover disc and tighten the T-bolt securely. For precision lathe work or heavy roughing cuts, it is advisable to secure the post with two dowel pins. The holes are pre-drilled.

Supplied with:

1 eccentric lever for No. 318000, 1 tool post key for No. 318100; 318200.

Technical description

maximum reach A	100 mm
maximum turning tool height h	45 mm
maximum drive power of lathe	11.04 kW
maximum cross slide width SB	180 mm
Height	105 mm
Bore \varnothing of the centering plate	16 mm

© Hoffmann GmbH Qualitätswerkzeuge

Bore \varnothing of the head	40 mm
Туре	C
Width	200 mm
Type of product	Steel toolholder

Accessories

Quick-change boring bar holder Type C40	318200 C40
Quick-change turning toolholder Type C40/150	318100 C40/150
Quick-change boring bar holder Type C50	318200 C50
Quick-change turning toolholder Type C40/170	318100 C40/170
Quick-change turning toolholder Type C32/150	318100 C32/150
Quick-change turning toolholder Type C32/170	318100 C32/170
Clamping arm complete suitable for toolholder head C	318150 C