



## Data transmission units, maximum number of measuring devices that can be connected: 5



### Order data

Order number	498904 5
GTIN	2050001958341
Item class	49H

### Description

#### Version:

For connection of measuring tools with Digimatic data outputs to a PC via a USB interface. The USB cable can also be used for the power connection. The data can be loaded under software control, or using the data button on the measuring tool, or using an optional pedal switch. Devices can be extended later.

Data transmission device for measuring tools with Digimatic and Opto-RS interfaces.

#### Supplied with:

USB data cable for connection to the PC. Supplied with adapter cable Opto RS No. 498908.

#### Optional extras:

Foot switch No. 498903.

Adapter cable for connecting measuring tools with Opto-RS interface No. 498908, set for connecting RS232 to a PC including power supply unit and connecting cable.

### Technical description

Number of Digimatic inputs	5
Connection foot-switch	yes
Number of USB outputs	1
Number of RS232 outputs	1
Opto-RS connection input	yes

Type of product

Data interface